



WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan
TEL/+886-4-2568 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

EOL number: EOL20210726

NotificationSubject:

- Issue Date : July.26, 2021
- Description : The IC vendor informed Boost Driver IC T79SV will be End of Life due to Wafer capacity issue.
- Effect of change : The following Winstar parts number

Standard Series	WF35L,WF35P,WF39D,WF39Q,WF43P,WF43W,WF52A,WF57P,WF70A2,WF70A7,WF70B,WF70G,WF70P,WF70Q
Custom Series	WJ101B2,WJ39E,WJ50F,WJ52C,WJ52H,WJ70B4,WJ70D3,WJ70G

- Last Order Date : Sep.5,2021 or Wafer sold out

We are working on replacement solutions suggested by vendor now and will provide further plan once available. Also, we will refer our previous usage quantity and prepare this IC stock for the upcoming 6 months order. But if you have an obvious high volume request, please consider to booking this material for your order plan.

Winstar appreciated your support in our products and we will continue to do our best to support and work with you. If there are any further questions, please feel free to contact your service sales person. Thank you!

Best regards,
Candice Wang