

WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan
TEL/+886-4-2588 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

Notification Subject:

■ Subject of Change: IC Vendor informed PCN driver IC SC7283-G4

■ Issue Date : July. 15th, 2021

■ Description: Due to original IC wafer capacity is completed full, IC vendor change wafer production. Also, we modified the VDDI range and added a set of capacitors from VCC to ground to strengthen the ESD ability..

■ Effect of Change: WF43W,WJ43B,WJ43C,WJ43Y Series

■ Planning Changing Time: Immediately after the current stock running out.

Panel Parts No.	Before Change ICSC7283321XXXXXXX00	After Change ICSC7283321XXXXXXX01
WS Module Parts No.	WF43W,WJ43B,WJ43C,WJ43Y Series	
FPC Appearance (FPC has been modified with the circuit according to the supplier's recommendations)	ROHS ROHS ROM ROM ROM ROM ROM ROM ROM RO	PS2TOVOAR300WA2G1X00 @B VOOM 1000 BHR000 CS SOA ATOL ATOL GOLD GOLD GOLD GOLD GOLD GOLD GOLD GO
Module		



WINSTAR Display Co., Ltd.


5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan
TEL/+886-4-2588 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

Appearance (effect keep same)



Module Appearance

(effect keep same)



Module Appearance





WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan
TEL/+886-4-2588 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

Winstar appreciated your support in our products and we will continue to do our best to support and work with you. If there have any further questions, please feel free to contact with your service sales window. Thank you!

Best regards, Candice Wang