





- Subject: Engineering design change of 0.96" TFT
- Issue Date : April, 21<sup>th</sup> , 2022
- Description: In order to improve the problem of backlight warping and peeling when customers attach FPC to the back of the module, we have enhanced the backlight design and structure.
- Effect of Change : WF0096 and WJ0096 Series
- Appearance Difference : Yes
- Function Difference : No
- Planning Changing Time: Immediately

Before Change	After Change
Defect issue: WF0096 Mechanism LC and LB are easy to peel off and warp	
	
Original Backlight frame	Backlight frame shrink





	
Backside of Original Backlight frame	New Backlight Appearance



# WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan

TEL/+886-4-2568 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

	
<p><b>Frontside Appearance</b></p>	<p><b>The frontside now has protection from shading tape; there is concave on the FPC.</b></p>
	
<p><b>Backside Appearance</b></p>	<p><b>The shading tape extends to the backside of the module.</b></p>

Winstar appreciates your support and we will continue to do our best to support and work with you. If you have any further questions, please feel free to contact us without hesitation. Thank you!

Best regards,  
Sales Department of Winstar Display