

Notification Subject: PCN for WF80

- Issue Date : April, 25th, 2022
- Description : WF80 Driver IC Nova NT39419 NT52001 EOL.
- Effect of Change : WF80B, WF80P, WF80Q Series
- Action Plan: Winstar finished testing and planning alternative IC FITI for further production units.
- Appearance Difference : Yes
- Function Difference : No
- Planning Changing Time : Immediately.



Before Change	After Change
IC : Nova S: NT39419 G: NT52001	IC : FITI S: EK9713 G: EK73002
	
FPC adds a QR code	





WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan

TEL/+886-4-2568 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw



FPC adds a solder mask tape



Protective film printing changes from "C" to "P"

Winstar appreciates your support, and we will continue to do our best to collaborate with you. If you have any further questions, please feel free to contact us without hesitation. Thank you!

Best regards,
Sales Department of Winstar Display