

WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan TEL/+886-4-2568 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

Notification Subject

- Subject of change : Engineering design change
- Issue Date : May 8, 2019
- Description: In order to strengthen characteristics of our 8" TFT module, and avoid the backlight opened soldering or backlight FPC Pin breakage issue. We changed the LCM internal backlight material and design.
- Module Parts Number : WF80B/WF80P/WF80Q Series
- Contents of change: The appearance of backlight FPC has slight difference, but the function test is all the same.
- Planning change Time: Immediately after the current stock running out.

Winstar appreciated your support and we will continue do our best to provide our products to customers. If there have further questions, please feel free to contact with us at any time. Thank you.

Best regards,

WINSTAR Display Co.,Ltd.